

To:

Mr. Paul Lambert, Principal, Canopy Oaks Elementary School

Ms. Staci Stephens, Assistant Principal, Canopy Oaks Elementary School

Mr. Alvin "Butch" Watkins, Director of Maintenance

Mr. Danny Allbritton, Director of Construction

From:

Mr. Juan E. Williams, Coordinator, Fire & Safett

Through:

Mr. LaRoderick E. McQueen, Building Official

Date:

March 18, 2019

Subject:

SREF Inspection for Canopy Oaks Elementary School (Ball Fields)

Attached to this memorandum is the State Requirements for Educational Facilities (SREF) Inspection Report for the above referenced facility. The report identifies the deficiencies and corrective actions for the entire site. The column labeled MOC identifies the entity responsible for correcting each deficiency, as follows:

- Line items with an M (Maintenance) in the MOC column are to be addressed by the Maintenance Department. Please do not submit work orders for the deficiency line items in the M (Maintenance) column. Upon completion of all work orders, please have Code Enforcement staff sign off to confirm completion.
- Line items with an O (Operational) in the MOC column are to be addressed by site based staff. These items need to be corrected within the proposed time allotment, prior to the follow-up inspection.
- Line items with a C (Construction and Capital Outlay) in the MOC column are to be addressed by the Construction/Facilities Department or a corrective action plan developed.

Notification of the completion or corrective action plan of the fore-mentioned deficient items need to be submitted to the Code Enforcement and Compliance Department. Please initial and date the line items under your area of responsibility on the provided report to confirm completion. You may email Ms. Deanetra S. Grissom at grissomd@leonschools.net or fax the report to (850) 617-1790, to her attention.

Please note a copy of this SREF inspection report will be forwarded to the Board.

**Additionally a separate inspection report has been provided for each portable at your site, in accordance with SREF Chapter 4
Section 4.4 (2) **

If you have any questions or comments regarding any items noted on this report, please feel free to contact Mr. Juan E. Williams at the Code Enforcement and Compliance Department at (850) 617-1814 or email at williams 20@leonschools.net. Thank you for your time and cooperation in this matter.

ATTACHMENT

Cc: Ms. S

Ms. Susan "Sue" Krual, Director of Elementary Schools (with attachments)

"Our Hands Keep Their Minds Working"

Code Enforcement and Compliance Department & Small Business Enterprise- 3420 West Tharpe Street - Suite 200 - Tallahassee, Florida 32303-1138

(850) 617-1838 · Fax (850) 617-1790

www.lcscodeenforcement@leoncountyschools.net

"The Leon County School District does not discriminate against any person on the basis of sex (including transgender status, gender nonconforming, and gender identity), marital status, sexual orientation, race, religion, ethnicity, national origin, age, color, pregnancy, disability, or genetic information."

	1		/2019			Ca		L Tri	. ~	Page 1 of	
	ECTION D		/			Canopy Oaks Elementary School (Ball Field) SCHOOL/FACILITY/CAMPUS 3250 Point View Road					
INSP	ECTOR:	Juan E.	Willian	าร	The second secon						
	1. /	(11,1)	111/1	~ 1							
INSPECTOR SIGNATURE SIGNATURE DATE					LEON COUNTY SCHOOLS	Tallahassee, Florida 32303					
INSPE				ATURE DATE	FACITLITIES & CONSTRUCTION DEPARTMENT						
/_		PE OF IN		ION	3420 W. THARPE ST., TALLAHASSEE, FL 32303	F.I.S.H. NUMBER					
×	FIRE	CASUA	LTY	SANITATION	COMPREHENSIVE SAFETY INSPECTION FISCAL YEAR: 2018-2019	037-1161-116					
Item #	Building Number	Room Number	M O C		Deficiency Description and Corrective Action Required	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT	
1	0000	000	0	Electrical panels	by the road are not fenced to restrict access to "Authorized Personnel Only".	1			Exterior Campus		
2	0000	000	0	There are no F.I	S.H. numbers anywhere.	1			Exterior Campus		
3	0000	000	0	Electrical panels	at fields are not secured at fence to restrict access to "Authorized Personnel Only".	1			Exterior Campus		
4	0000	000	0	GFCI cover is d	amaged at back door of concessions.	1			Exterior Campus		
5	0000	000	0	Fencing around	holding pond is damaged in multiple locations.	1			Exterior Campus		
6	0000	000	0	Drains througho	nt site are not (ADA) Compliant (covers).	1			Exterior Campus		
7	0000	000	0	Remove exposed	maintenance equipment piled up near shed by road (old lumber and other debris).	1			Exterior Campus		
8	0000	000	0	Concrete bumpe	s are damaged with exposed rebar near parking space.	1			Exterior Campus		
9	0000	000	0	Electrical panels	by tennis courts are not fenced.	1			Exterior Campus		
10	0000	000	0	Light pole by pla	yground cover is loose and rusted.	1			Exterior Campus		
11	0000	000	0	Plants by tennis	courts poses a potential hazard (berries).	1			Exterior Campus		
12	0000	000	0	No Emergency C	all Box present.	1			Exterior Campus		
13	0000	000	0	Gate handle on fe	ence in dugout is broken. (Field #2)	0			Exterior Campus		

Printed: 3/20/2019 - 8:37 AM

		3/18/2	2019								Page 2 of		
INSPE	CTION D		2017		LEON COUNTY SCHOOLS			Canopy Oaks Elementary School (Ball Field)					
		Juan E. V	Villiam	<u> </u>				SCHOOL/ FACILITY/CAMPUS					
								3250 Point View Road					
Mene	0T00 0101							Tallahassee, Florida 32303					
INSPE	CTOR SIGN			TURE DATE	FACITLITIES & CONSTRUCTION DEPARTMENT								
[AA]	-	PE OF IN	-	ON	3420 W. THARPE ST., TALLAHASSEE, FL 32303			F.I.S.H. NUMBER					
FIRE CASUALTY SANITATION					COMPREHENSIVE SAFETY INSPECTION								
			8.4		FISCAL YEAR: 2018-2019 037-1161-116				6				
item #	Building Number	Room Number	M O C		Deficiency Description and Corrective Action Require	<u>d</u>	# of Times Deficiency Previously Cited	Schedule for Correction No Later Than	Re- Inspection Correction Date	Site-Wide Building- Wide Exterior Campus or Portable	REMARKS CODE REFERENCE MAINTENANCE ASSIGNMENT		
14	0000	000	0	Drain grates at B	ig Field are to deep creating tripping hazard.		0			Exterior Campus			
15	0000	000	0	Ant beds are pre-	sent inside playground area.	0			Exterior Campus				
16	0000	000	0	Padding is peeling	ng from platforms on playground equipment exposing hard metal.	0			Exterior Campus				
17	0000	000	0	Handrail going u	p to Announcers Box on field # is loose from flange.	0			Exterior Campus				
END OF SREF INSPECTION REPORT													
A re-insp	A re-inspection of the identified deficiencies will be preformed approximately 60-90 days subsequent of inspection date. Re-Inspection Date:												
The principal shall hold at least one (1) fire drill during each month, with an additional drill being held within the first 30 days of school.							NO						
Signature of facility administrator attesting to Fire Evacuation Drills and review of inspection report acknowledging awareness of discovered deficiencies: Date of Acknowledgement:													
X State Slepho Leon County School/Site Administrator													
											- 1		